ECS Configuration Change Request					Page 1 of	Р	age(s)	
1. Originator	2. Log Date:	3. CCR #:	4.	Rev:	5. Tel:	6. Rm #	7. Dept.	
Byron V. Peters	03/26/03	03-0213		_	301/883-4077	2013	SE	
8. CCR Title: Test SGI Patch 5032 in VATC and PVC								
9. Originator Signature/Date			10. Class		11. Type:	1. Type: 12. Need Date: 3/26/03		
Byron V. Peters /s/ 3/26/03			IN		CCR			
13. Office Manager Signature/Date Carolyn Whitaker /s/ 03/26/03			14. Category of Change Initial ECS Baseline Doc		_	15. Priority: (If "Emergency" fill in Block 27). Emergency		
o . ,				7. Schedule 18. CI(s) Affected: mpact:				
19. Release Affected by this Change: 20. Date due to								
6A				None - Under 100K				
22. Source Reference: ⊠NCR (attach) □Action Item □Tech Ref. □GSFC □Other: ECSed37050								
23. Problem: (use additional Sheets if necessary) BDS has a problem with flow control when using Gigabit Ethernet. The driver sends the wrong error to the application which is ignored resulting in potentially bad data.								
24. Proposed Solution: (use additional sheets if necessary) SGI has released patch 5032 to fix this issue. Please install on t1acg04 and t1drg03 initially. If that test works, apply to p0acg05, p0drg01, p0drg04, p0icg01, p0spg07, and p0teg01. Tar file is on lemmings. cksum data: 2807963045 215040 patch5032.tar								
25. Alternate Solution: (use additional sheets if necessary) N/A								
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Continued performance deficit at GES DAAC.								
27. Justification for Emergency (If Block 15 is "Emergency"): Needed at GES DAAC as soon as possible but must be tested with the custom code in the PVC.								
28. Site(s) Affected: DF DVC VATC DEDC GSFC LaRC NSIDC SMC AK JPL DEOC DIDG Test Cell Other								
29. Board Comments:				30. V	Vork Assigned T	o: 31. CCF	R Closed Date:	
32. EDF/SCDV CCB Chair (Jason Wardenburg /s/	(Sign/Date): D 3/26/03 ER	Pisposition: RB	oproved A	App/Co	om. Disapproved	d Withdraw	Fwd/ESDIS	
33. M&O CCB Chair (Sign/	Date): D		ition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS					
34. ECS CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERE								
		Fwd/ESDIS						

CM01JA00 Revised 8/2/02 ECS/EDF/SCDV/M&O